

LOSS CONTROL SURVEY

Company Name: Top Gun Roofing, Inc. No. of Employees: 2
FRSA Account #: 33663
Address: 5570 Florida Mining Blvd S., Ste 501 Jacksonville, FL
Loss Control Consultant: Matt Savin Date: 3/26/2015

<input checked="" type="checkbox"/> Site <input type="checkbox"/> Shop <input type="checkbox"/> Consult	Site Address: 3449 Uphill Terrace Jacksonville, FL
<input type="checkbox"/> Safety Meeting	Description: Residential, Shingle, Re-roof, 7:12 Pitch

Ladders & Scaffolds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fire Prevention	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hot Work (kettle, torch & welding)	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Hoists, Lifts, & Cranes	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Housekeeping	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Material Handling and Storage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Personal Protective Equipment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Water & Sanitation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety & First Aid Equipment	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Motor Vehicles	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hand, Power, & Pneumatic Tools	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Perimeter & Fall Protection	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Walking & Working Surfaces	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Machine Safety	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Electrical Hazards	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Emergency Preparedness	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Yard	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Hazard Communications & MSDS	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Safety Awareness	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Safety & Labor Information	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Lock
Out/Tag Out	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Warning Placards	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Previous Recommendations	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Cooperation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Other - See Comments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Comments: Very Knowledgeable Crew

- 1) Knowledgeable Employees
- 2) Good housekeeping - All trash and debris contained.
- 3) Water and sanitation were in place.
- 4) Ropes and Harnesses in Place for Fall Protection.
- 5) Company vehicles in good working condition.
- 6) Ladder extended 3' above the roof, and was tied off.
- 7) All tools and equipment properly guarded.
- 8) Employees were courteous and cooperative during the inspection.

Recommendations:

None at this time

Great Job!!!

